


45°エルボ



単位:mm

| 呼び径 (A) | 呼び径 (B) | A ₃ |
|---------|---------|----------------|
| 6 | 1/8 | 16 |
| 8 | 1/4 | 17 |
| 10 | 3/8 | 19 |
| 15 | 1/2 | 21 |
| 20 | 3/4 | 25 |
| 25 | 1 | 29 |
| 32 | 1 1/4 | 34 |
| 40 | 1 1/2 | 37 |
| 50 | 2 | 42 |
| 65 | 2 1/2 | 49 |
| 80 | 3 | 52 |
| 100 | 4 | 64 |